

Revise History

Date	Version	Revision
11/25/2025	1.08.01.15R8	1. Resolved the issue where SDG800 bandwidth upgrades did not take effect immediately and required a restart.
3/10/2025	1.08.01.15R7	<ol style="list-style-type: none"> 1. Solve the problem that the sync signal is output when the channel is not turned on 2. After the sweep is completed, the output frequency is modified to stay at the initial frequency of the sweep.
2/22/2023	1.08.01.15R3	1. Fix the compatibility bug of Rev.E hardware, and generally do not need to upgrade.
8/5/2022	1.08.01.15R2	<ol style="list-style-type: none"> 1. Fixed the bug that startup occasional failures 2. Fixed the bug of burst sync output exception 3. Fixed the bug that may not output when switch the waveform after the burst is turn off
12/3/2020	1.08.01.15	<ol style="list-style-type: none"> 1. Supported to automatically enable the output after power-on: Utility Output Setup Power on State 2. Compatible with Rev.E hardware
7/16/2019	1.08.01.13R9	Fixed the abnormal display issue during start-up on some units with previous releases. It is not necessary to update to this version if the unit has no such a problem.
8/30/2018	1.08.01.13R6	Fixed the incorrect sweep direction bug (2018/05/23-115276)
3/21/2018	1.08.01.13R5	<p>It is strongly recommended to update to the latest release because in some previous release exists some serious bug which could cause the generator never startup</p> <ol style="list-style-type: none"> 1. Supported system recovery from the U-disk 2. Supported Rev.C hardware with Over Voltage Protection
6/7/2016	1.08.01.12R2	Fixed several bugs <ol style="list-style-type: none"> a) A bug in P12R1 which could cause the update to fail b) Some typo in English help system
3/7/2016	1.08.01.12R1	Fixed several bugs <ol style="list-style-type: none"> a) A bug in file system could cause the generator never startup b) Can not wake up from screen saver from

Date	Version	Revision
		time to time
11/9/2015	1.08.01.11	1. Re-open the self-calibration function
		2. Fixed a bug which may cause the generator can not startup
		3. Fixed several other bugs